

ZONE 3 UPDATE



PUBLIC WORKS DEPARTMENT

GROUNDS MAINTENANCE DIVISION

Chamber of Commerce

Landscape Restoration

TECHNICAL SERVICES

E. ISB Streetscape

Location: Halifax Ave. to Atlantic Ave.
FDOT - Sidewalk, drainage, resurfacing and landscaping

Dickerson Center - ADA Restroom Upgrades

Remodeled non-compliant restrooms

Public Works 950 Bellevue Generator Install

Boardwalk Trail Repair - Bookland Bridge

Repair from Hurricane Ian/Milton

Riverfront Park Day Dock Repair

Repair from Hurricane Ian/Milton

Manatee Island Floating Dock Repair

Repair from Hurricane Ian/Milton

Halifax Harbor Marina Repair

South side repair from Hurricane Nicole

Coast Guard Auxilliary Building Remodel

Electric Vehicle Charger Installations

Henry Lee Park Basketball Court Resurfacing

 COMPLETE  ONGOING



QUANITA MAY
(386) 671-8003



ZONE 3 UPDATE



PUBLIC WORKS DEPARTMENT

STREETS MAINTENANCE DIVISION

Turie T. School - ADA Sidewalk and School Zone Improvements

Loomis Ave. at Keech Street
ADA bump outs with crosswalks

Loomis Ave. at Caroline Street
ADA bump outs with crosswalks

Russell Dr. at South Street
ADA bump outs with crosswalks

847 Orange Ave. Enterprise Center

Concrete replacement

Hobart and Michigan

Sidewalk and curb replacement

Lenox Dog Park

Concrete pad and site grading for new shade structure

Coquina rock install

Paving Program Completed

Road Name	From Address	To Address
Davis St.	Atlantic Ave.	Grandview Ave.
Goodall Ave.	Peninsula Dr.	Goodall Ave. (formerly Sunset Dr.)
Goodall Ave. (formerly Sunset Dr.)	Goodall Ave.	Vermont Ave.
Goodall Ave.	Goodall Ave.	End of road
Revalo Blvd.	Atlantic Ave.	Grandview Ave.
Revalo Blvd.	Grandview Ave.	Peninsula Dr.
Ribault Ave.	Atlantic Ave.	Grandview Ave.
Ribault Ave.	Grandview Ave.	Peninsula Dr.
Vermont Ave.	Atlantic Ave.	Grandview Ave.
Vermont Ave.	Grandview Ave.	Peninsula Dr.
Vermont Ave.	Peninsula Dr.	Goodall Ave. (formerly Sunset Dr.)
Vermont Ave.	Goodall Ave. (formerly Sunset Dr.)	End of road
Daytona St.	Mullally St.	Michigan Ave.
Daytona St.	Michigan Ave.	Fairview Ave.
Daytona St.	Michigan Ave.	Michigan Ave.
Michigan Ave.	Segrave St.	Ridgewood Ave.

■ COMPLETE ■ ONGOING

ZONE 3 UPDATE



UTILITIES DEPARTMENT

PROJECTS IN DESIGN & CONSTRUCTION

Butts Pond Stormwater Pump Station Improvements

Hardening upgrades to mitigate flooding risks, including pump raising, redundancy, and emergency generator.

Location: 21-acre stormwater pond near Nova Road.

Design Cost: \$64,931

Construction Cost: \$589,931

Funded by FDEP Hurricane Recovery Grant: \$625,000;

Water Sewer Revenues: \$64,931.

Lift Station No. 7 Replacement

Flood-proof design elevates key equipment 2 feet above 100-year flood elevation.

Location: Low-lying area near Nova Canal.

Design & Construction Cost: \$1,200,000

Funded by FDEP Grant: \$1,015,000;

Water/Sewer Revenues: \$300,658.

Lift Station No. 8 Replacement

Flood-proof design similar to No. 7.

Location: 1210 Bellevue Ave.

Design & Construction Cost: \$978,000

Funded by FDEP Grant: \$1,015,000;

Water/Sewer Revenues: \$118,600.

Lift Station No. 27 Structural Improvements

Replacement of wetwell top and improved ventilation/access.

Design Cost: \$15,316

Estimated Construction Cost: \$150,000.

COMPLETED PROJECTS

FDOT-ISB SR600 Halifax River Bridge to SR-A1A (Phase II 437942 P-6800)

Utility relocations for the City, with associated costs pending.

Status: Completed February 2025, in closeout phase.

Volusia County E. ISB Beach Ramp Improvements

City staff extended 6" watermain to provide service to new beach facility bathrooms.

FIELD MAINTENANCE PROJECTS COMPLETED

Sewerline Maintenance

CIPP Projects: Rehabilitated various sections of 8"-10" VCP pipe (Total: 6,460 LF).

Sewerline Inspections: Cleaned and CCTV-inspected 2,580 LF of 10"-12" VCP pipe.

Lift Stations

Lift Station 001 Rehabilitation: Full rehabilitation and improvements completed.

Water Distribution

Fire Hydrants: Inspected and tested 194 hydrants (FDEP & NFPA Compliance).

Potable Valves: Inspected and verified 712 valves for emergency readiness.

Stormwater Maintenance

S. Palmetto Stormwater Pipe: Cleaned and CCTV-inspected 754 LF of 12"-36" RCP pipe.

■ COMPLETE ■ ONGOING